

domin karin bayani, duba www.metafridge.org/support

CFD-50 da CFD-50 SDD na Aucma Firinji an yi su ne da fasahar MetaFridge don kare alluran rigakafi koda babu tabataccen wutan lantarki. Kulawa mai inganci ga frinjin nada matukar amfani wajan tabbatar da cewa yana kyakkyawan aiki.



120 hrs holdover at 43 °C ambient



MASU FASAHAR GYARA KAWAI

Kafin a fara amfani da frinjin, a bude marfin dake a sama, sai a zuba lita 32 na ruwan sha mai kyau

Yanda ake zuba ruwa a cikin

Kowace shekara a bincika matakin ruwa kuma a kara ruwa har sai ya kawo kasan bututun zuba ruwan



A bada tazazar 10cm tsakanin frinji da bango




A dinga goge raga-ragan kwandensa da kasa na bayan frinjin kowani wata



Kirkira da Aika Rahoton ta VARO



Stabiliza da injin mai ba da kariya suna haɗe da igiyar wutan lantarki kai tsaye zuwa bango. Ba sai an hada wata stabilizer ta daban ba.



SDD ONLY

Sai a kunna frinjun ta wurin sauya wutar lantarki (Kar a taba wajan masu fasahar aiki frinji)




12V port
USB ports
EHC
(masu fasaha da gyaran frinji kawai)



MA'AIKATAN ASIBITI



Don umarnin yadda ake amfani da 30DTR, sai a duba baya



Duk wuraren da ke cikin sashen sanyi an amince da ajiyar maganin alurar riga kafi. Yi amfani da faranti da aka tanada don kiyaye ajiyar maganin daga taba bango.



A BUDE LOKACIN DA AKE BUKATA KAWAI

A adana allurai kawai a cikin frinji, banda abinci ko abin sha



A goge danshi kamar yadda ake bukata. Bincika akwatunan da roba a jikin kofa guda biyu don lalacewa, a kowane wata a goge su a tsaftace




A tabbatar da kofar frinji a rufe kuma a matse sakata lokacin da ba'a amfani dashi



SDD ONLY

kura da kasa a kan fanel tana rage karfin wutar da frinji ke samu



Don hana asarar wuta, a tsaftace bangarorin fanel na hasken rana kowane wata ta amfani da ruwa da tsimma mai laushi



SHAFIN DA AKE CIKI

Fitilar Nuna Alama

Walwalin jar fitila:
Kararrawa

Kore:
Injin Kwamfreso na aiki

Kwanan Wata
ko ranar bayanin rahoto
a cikin shafin tarihi

Samuwar Wutar Lantarki

CFD-50 Mains Power in-range	NO power	CFD-50 SDD Power in-range	NO power

Tsawon lokaci na kwanaki 30

- Tsakiya**
Babu kararrawa
- Hawa sama**
Kararrawa ta tsanani da karfin zafi
- Sauka kasa**
kararrawa ta tsananin sanyi



KARARRAWA MAI AIKI YANZU

kararrawa tana nuna yanayin da zai iya barazanar kiyaye lafiyar alurar. A lokacin da yake akwai yayin kararrawa, toh zai nuna jar fitila, sannan za a sami sauti mai kararrawa, kuma nunin zai shaida nau'in kararrawar da kuma tsawon lokacin ta.



Taba dan yayi shuru

Ire 'iran kararrawa

Matsala

Tsananin zafi	(10 hrs > 8 °C)
Tsananin sanyi	(1 hr < -0.5 °C)
Budewar kofa	(> 20 minutes)
karanci rike sanyi	(< 2 days remain)
babu rikon sanyi	(0 days remain)



SHAFIN TARIHI

Tarihi
Yana nuna iyakar sanyin ko zafi na wanan rana

Alamar
Yana nuna matsayi a cikin bayani rahoto

Kibiyoyin L da R
Zasu bada damar motsawa baya ko gaba ta hanyar bayanar rahoto na yau da kullun

TAKAITACCEN TARIHIN

KARARRAWA NA YAU